



Trevor Boundy <trevor@boundy39.com>

35 Second 1/2A Fubar 600 - Wing Left Inner Panel Framing (Part 2) (Correction)

1 message

Tandy Walker <rdb435021@icloud.com>
To: Trevor Boundy <jtboundy@dcsi.net.au>

Tue, M

Good Morning Trevor,

I made a mistake in Report No. 35. Please substitute the picture below for the one that has the angle at 5.98° . As you can clearly see it should be $(90 + 5.98) = 95.98^\circ$ Tandy

