



Trevor Boundy <trevor@boundy39.com>

FW: 48 Tip Panel Top Spars

1 message

Tandy Walker <rdb435021@icloud.com>
To: Trevor Boundy <jtboundy@dcsi.net.au>

5 February 2022 at 00:22

From: Tandy C. Walker [mailto:tandyw@flash.net]

Sent: Tuesday, September 12, 2006 11:33 AM

To: Angel, Bob <samrcflier@verizon.net>; Anderson, Joe <joe.anderson@lmco.com>; Herbon, Alfredo <aherbon@coopenet.com.ar>; Augustus, Bruce <baugustus@cox.net>; Beecroft, Robert K. <nffsflyer@adelphia.net>; Bruno, Steve <Steve3219@aol.com>; Burk, Jerry <chjerryburk@mindspring.com>; Crawford, Key <rebelc@wtrt.net>; Gies, Karl <skyland@midrivers.com>; Greenhalgh, Jim <jg1984@earthlink.net>; Hilbert, Meryl <hilbertmm@knology.net>; Hiner, Jack <j.hiner@comcast.net>; Kruse, Larry <aircats@lvcisp.com>; Martin, Gerald <geraldmartin@wtrt.net>; Matthews, Jeff <jeffmatthews1@yahoo.com>; Montes, Sergio <montes@iinet.net.au>; O'Reilly, Jim <KSFreeflit@aol.com>; Pardue, Albert M. <AWPARDUE@aol.com>; Taylor, Bill & Gail <taylorxtwo@cox.net>; Walker, T. Cy <cwalker@kenyon.com>; Shilen, Ed & Charlene <ed15char@aol.com>; Matthews, Ray & Frances <MATTHEWSAV@aol.com>; Dan McLeod <mcgdci@adelphia.net>; Smith, Keith <info@pacificsailplanes.com>; Gene Wallock <velinak@sbcglobal.net>

Subject: 48 Tip Panel Top Spars

Over the weekend I managed to get all three top spars installed on the left wing tip panel. The ribs spar notches did not exactly line up due to a combination of slight errors in my rib patterns, the transfer to balsa, and cutting out the actual ribs. The picture below shows my approach to correcting this problem on the front top spar. I used a length of 1/2" aluminum angle, which I held in place along the forward edge of the notches with two steel block squares as shown below. I marked each misaligned rib and then cut it out. I also had to do the same thing on the back edge of the notches.



This shows all three top spars installed on the left wing tip panel. Notice how straight they are. :O)

