



From: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)
 To: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)
 Date: 3/19/2018 3:50:58 PM
 Subject: 88 Lancer 850 - Horizontal Tail Construction (Part 5)

Report No. 88
New Cyclone Lancer 850
 March 19, 2018

This morning Sue and I worked out at the fitness center. When we got home we moved all of our temperature sensitive plants out of the garage onto the patio now that the weather has finally warmed up here. I cleaned up the garage, replaced the left rear yellow turn signal bulb on Sue's PT Cruiser, and then it was time for lunch. After lunch I finished framing up the stab this afternoon as shown below. Notice that the diagonal bracing was left out. This will be added in after the stab frame is removed from the plan in order to get the correct vertical centering.



This close up of the stab's center section shows the stab's 3/8" fin slot formed by the two 1/8" central ribs. Notice that the center section of the 1/16" bottom balsa planking will also be added in after the stab frame is removed from the plan.



This shows the trial fit of the of the 3/8" fin base in the stab's center slot.....Tandy

