



Trevor Boundy <trevor@boundy39.com>

89 Second 1/2A Fubar 600 - Weekend Status1 message

Tandy Walker <rdb435021@icloud.com>

To: Tandy Walker <rdb435021@icloud.com>

Report No. 89

*Second 1/2A Fubar 600**May 9, 2020*

I have removed the silk covering over the push rod exits and all of the various ho fuselage. 2-56 and 4-40 taps were used to run the threads on all of the threaded painting mandrel that bolts to the firewall shown below was made to provide a har comes time to spray the final thin coat of Klass Kote on the fuselage's silk. Now w 40D/60T clear nitrate dope brushed on the silk, the color is getting close to I w brush on the two final coats of clear dope, one in the morning and one just before will have 10% Randolph's retarder add to the dope mixture to provide extra penet coats.....Tandy

