

From: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

To: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

Date: 12/6/2017 11:15:37 AM

Subject: 13 Lancer 850 - Straightening Bowed Leading Edges

New Cyclone Lancer 850

December 6, 2017

The use of water sprayed on the 3/8" X 1" X 48" balsa leading edges that were clamped in a reverse bow and allowed to dry straightened them out nicely. As a precaution against reoccurrence, I put them together and clamped them to the edge of work table in four places as shown below. I used an aluminum straight edge to make sure the clamps were lined up in a straight line.....Tandy

