

From: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

To: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

Date: 2/12/2018 1:58:02 PM

Subject: 59 Lancer 850 - Top Left Leading Edge Planking (Part 5)

Report No. 59

*New Cyclone Lancer 850*

*February 12, 2018*

I spent the better part of this morning planking the top left wing panel's leading edge as shown below. By now, you are quite familiar with the procedure I am using so I won't repeat it again here. However, using Alfredo Herbon's procedure of planking the top of the leading edge last, the wing is well supported with it's leading and trailing edges flat on the work table. To paraphrase Alfredo's words:

*This way, if a little misalignment (twist) is accidentally introduced while doing the bottom planking, it will be corrected with the top curved planking that closes the D-Box while the wing panel securely supported and aligned on the board (work table).*

.....Tandy.....

