

From: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

To: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

Date: 2/14/2018 2:53:00 PM

Subject: 62 Lancer 850 - Planking the Center Section (Part 2)

Report No. 62

New Cyclone Lancer 850

February 14, 2018

In Report No. 48, a signature label with my name, address, and date was glued on the front side of the rear plywood dihedral brace and closed up inside when the front dihedral brace was glued on. Since that label will never be found inside that plywood box, a second signature label was glued to bottom of the center section's top planking located as shown below.



This close up shows the center section's top planking complete.



This picture of the wing was taken to show all of wing's top planking. The bottom of the center section's planking will be completed tomorrow.....Tandy

