



Trevor Boundy <trevor@boundy39.com>

120 Lancer 850 - Strips for Fuselage Standoffs

1 message

Tandy Walker <rdb435021@icloud.com>
To: Tandy Walker <rdb435021@icloud.com>


Wed, Apr 25, 2018 at 1:28 AM

Report No. 119


New Cyclone Lancer 850

April 24, 2018


The fuselage has a 1/8" X 3/16" stringer in the center of each side as shown below.



Each of the fuselage's four longerons require "standoff" balsa strips to prevent the covering from sticking to the vertical, diagonal, and cross members in the fuselage frame when it is stretched over the 1/8" X 3/16" side stringers up and down to the edge of the longerons. The 1/32" X 1/4" standoff is illustrated in the drawing below.



Several years ago a modeler, whose name I cannot recall now, made several extremely well-crafted balsa strips and I was able to purchase the one shown below.



Yesterday afternoon 1/32" balsa sheet was stripped into a number of 1/32" X 1/4" strips to be used for the longeron standoffs later after the bulkheads have been installed.....Tandy

