



Trevor Boundy &lt;trevor@boundy39.com&gt;

---

**FW: 126 Stinson Reliant SR-7 - Double Covering Doping**

1 message

---

**Tandy Walker** <rdb435021@icloud.com>  
To: Trevor Boundy <jtboundy@dcsi.net.au>

Fri, Jul 10, 2020 at 5:25 A

---

**From:** Tandy Walker [mailto:[aerotan1503@outlook.com](mailto:aerotan1503@outlook.com)]  
**Sent:** Saturday, February 06, 2016 12:27 PM  
**Subject:** 126 Stinson Reliant SR-7 - Double Covering Doping*Stinson Reliant SR-7**February 6, 2016*

*I closed my report No. 125 a week ago indicating that I had a sore throat and a bad cough that was getting progressively worse. After spending a couple of days and nights sick in bed coughing my head off, I went to a CVS Minute Clinic for an examination. It turned out not to be a cold or allergies at all, but rather an infection in my left ear. This was causing a drainage into my throat making me cough continuously and feel terrible in general. A regiment of antibodies and cough pills was prescribed, which is slowly improving the situation, but I am still not a 100%.*

However in spite of feeling so poorly, I have managed to brush on 4 additional coats of 30/70 clear and tinted nitrate dope on all of the Stinson's parts with a day's drying time between coats as shown below. A 5<sup>th</sup> coat with 15% retarder added for penetration was brushed on yesterday and will be allowed to dry for several days while my health continues to improve. Once dry the next step will be to remove the double covering that is over all of the various holes and openings in all of the parts.....Tandy

