



Trevor Boundy <trevor@boundy39.com>

49 Cleveland Cloudster 600 - Preglued Wing Tips (Part 2)

1 message

Tandy Walker <rdb435021@icloud.com>
To: Tandy Walker <rdb435021@icloud.com>


Fri, Sep 18, 2020 at 1:05 AM

Report No. 49

Cleveland Cloudster 600

September 17, 2020

This morning removed the two wing tips from the plans as you can see below and sanded the inside and outside edges at the joints to match. Notice the highlighted tip joint.



This is a close up of the highlighted joint to show how the inside and outside contour edges match.....Tandy



