

From: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

To: ["Tandy Walker" <rdb435021@icloud.com>](mailto:rdb435021@icloud.com)

Date: 3/3/2018 2:34:11 PM


Subject: 78 Lancer 850 - Planking Shelf and Bulkhead C Installation

Report No. 78


New Cyclone Lancer 850

March 3, 2018

The top of the fuselage from the firewall back to C bulkhead will be planked with 1/8" balsa. So there are "planking shelves" on the front face of bulkhead C and the back face of the firewall as illustrated below.



The top of the paper pattern for the C bulkhead shown below was used to make the pattern for the planking shelf.



The planking shelf below was cut out of 1/8" sheet balsa.



The planking shelf was glued to the front face of the C bulkhead as shown below, which completes the C bulkhead.



The C bulkhead was then clamped and glued in place with aliphatic glue as shown below. Notice the extra 1/4" sq. bottom cross member to support the narrow bottom of the C bulkhead.



This picture shows the C bulkhead and its planking shelf installed in the fuselage's frame work.....Tandy

